

## Notice of product retrofit

Category: Other

Product: platform lift,  
straight rack and pinion models

Brand: Garaventa Lift

Name: XII

Affected Years: 2006 – 2013

Risk type: Overload



Garaventa Canada Ltd has identified certain models of inclined platforms that require an upgrade. The upgrade must be installed by a factory authorized technician and is being provided, free of charge. The upgrade is required to prevent any harm or injury from an unlikely or severe overload situation.

We have not been able to identify the location of all lifts. To check if your lift requires the update, please contact our Service Center via email [technicalsupport@garaventlift.com](mailto:technicalsupport@garaventlift.com) or +1 604 594 0422 by indicating the serial number and full address of the unit.

Measures taken: A Technician will need approximately 2 hours on an operational unit to complete the work. Garaventa Lift or their representative will not be performing any other service, maintenance or alterations other than that specified by the manufacturer for the upgrade.